MONTANA WELL LOG REPORT

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights is the well owner's responsibility and is NOT accomplished by the filing of this report.

Other Options

Go to GWIC website
Plot this site in State Library Digital Atlas
Plot this site in Google Maps
View scanned well log (4/3/2009 12:53:07 PM)

Site Name: TYLER KARL
GWIC Id: 152138
DNRC Water Right: 95923

Section 1: Well Owner(s)

1) TYLER, KARL (MAIL)
10115 MULLAN RD
MISSOULA MT 59802 [08/28/1995]

Section 2: Location

Township	Range	Section	Quarter Sections
13N	19W	20	NW¼ NE¼

County	Geocode
MISSOULA	

Latitude	Longitude	Geomethod	Datum
46.876392	-114.026899	TRS-SEC	NAD83

Ground Surface Altitude	Ground Surface Method	Datum	Date

Addition	Block	Lot

Section 3: Proposed Use of Water

DOMESTIC (1)

Section 4: Type of Work

Drilling Method: ROTARY
Status: NEW WELL

Section 5: Well Completion Date

Date well completed: Monday, August 28, 1995

Section 6: Well Construction Details

There are no borehole dimensions assigned to this well.

Casing

From	To	Diameter	Wall Thickness	Pressure Rating	Joint	Type
-2	60	6				STEEL

Completion (Perf/Screen)

From	To	Diameter	# of Openings	Size of Openings	Description
60	60	6			OPEN BOTTOM *

Annular Space (Seal/Grout/Packer)

From	To	Description	Cont. Fed?
0	0	BENTONITE	

Section 7: Well Test Data

Total Depth: 60
Static Water Level: 30
Water Temperature:

Air Test *

30 gpm with drill stem set at _ feet for 1 hours.
Time of recovery _ hours.
Recovery water level _ feet.
Pumping water level _ feet.

** During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.*

Section 8: Remarks

JEROMES FILE NO: 6313

Section 9: Well Log

Geologic Source

112ALVM - ALLUVIUM (PLEISTOCENE)

From	To	Description
0	2	SOIL
2	30	SAND GRAVEL COBBLES
30	60	SAND GRAVEL

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name:
Company: JEROMES DRILLING CO
License No: WWC-249
Date Completed: 8/28/1995

MONTANA WELL LOG REPORT

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights is the well owner's responsibility and is NOT accomplished by the filing of this report.

Other Options

Go to GWIC website
Plot this site in State Library Digital Atlas
Plot this site in Google Maps
View scanned well log (4/3/2009 12:51:50 PM)

Site Name: LAFRAY CURTIS
GWIC Id: 68897

Section 1: Well Owner(s)

1) LAFRAY, CURTIS (MAIL)
2011 RIVER RD
MISSOULA MT N/A [04/09/1972]

Section 2: Location

Township	Range	Section	Quarter Sections
13N	19W	20	NW¼ NE¼

County	Geocode
MISSOULA	

Latitude	Longitude	Geomethod	Datum
46.876392	-114.026899	TRS-SEC	NAD83

Ground Surface Altitude	Ground Surface Method	Datum	Date
3223			

Addition	Block	Lot

Section 3: Proposed Use of Water

DOMESTIC (1)

Section 4: Type of Work

Drilling Method: CABLE
Status: NEW WELL

Section 5: Well Completion Date

Date well completed: Sunday, April 9, 1972

Section 6: Well Construction Details

There are no borehole dimensions assigned to this well.

Casing

From	To	Diameter	Wall Thickness	Pressure Rating	Joint	Type
0	57	5				STEEL

Completion (Perf/Screen)

From	To	Diameter	# of Openings	Size of Openings	Description
57	57	5			OPEN BOTTOM *

Annular Space (Seal/Grout/Packer)

There are no annular space records assigned to this well.

Section 7: Well Test Data

Total Depth: 57
Static Water Level: 6
Water Temperature:

Air Test *

45 gpm with drill stem set at _ feet for 2.5 hours.
Time of recovery _ hours.
Recovery water level _ feet.
Pumping water level 9 feet.

** During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.*

Section 8: Remarks

Section 9: Well Log

Geologic Source

111ALVM - ALLUVIUM (HOLOCENE)

From	To	Description
0	2.5	TOPSOIL
2.5	7	COARSE GRAVEL AND SOME SAND
7	25	COARSE GRAVEL SAND AND WATER
25	29	SAND AND WATER
29	43	SAND GRAVEL AND WATER
43	48	RED CLAY NO WATER
48	52	SAND AND WATER
52	57	GRAVEL AND WATER

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name:
Company: PICKENS
License No: WWC-71
Date Completed: 4/9/1972